**International Journal of Advanced Materials Research**
Vol. 1, No. 2, 2015, pp. 41-44
http://www.aiscience.org/journal/ijamr

# Corrosion Studies of Al7075 / Silicon Carbide Composites in Mixture of Sodium Hydroxide and Sodium Chloride Solutions

**Pruthviraj R. D.***

R&D Centre, Department of Engineering Chemistry, RajaRajeswari College of Engineering, Visvesvaraya Technological University, Bangalore, Karnataka, India

## Abstract

The aim of the research work was to investigate the corrosion behaviour of Silicon Carbide(SiC) reinforced aluminium 7075 metal matrix composites (MMCs) in a mixture of alkaline and salt solution using weight loss method. The mixture alkali and salt solution used is mixture of sodium hydroxide and sodium chloride solutions. The composites are manufactured by liquid metallurgy technique using vortex method. Aluminium 7075 / SiC MMCs containing 2, 4 and 6 weight percentage of SiC particulates are casted. The corrosion characteristics of Aluminium 7075 /SiC composite and the unreinforced alloy were experimentally assessed. The corrosion test was carried out at different concentrations of mixture of sodium hydroxide and sodium chloride solution at a concentration of 0.025M, 0.05M and 0.1 M solutions for different exposure time. The results indicated that corrosion rate of metal matrix composites was lower than that of matrix material Al 7075 under the corrosive atmosphere irrespective of exposure time and concentration of corrodent. Aluminium 7075 / SiC composite become more corrosion resistant as the SiC content is increased. This is because of the formation of stable oxide layer over the specimens. Scanning Electron Microscopy (SEM) show the degree of attack of alkaline solution on the surface of the investigated material.

## Keywords

Metal Matrix Composite (MMCs), Silicon Carbide, Corrosion Loss, Weight Loss

Received: April 7, 2015 / Accepted: April 26, 2015 / Published online: May 15, 2015

@ 2015 The Authors. Published by American Institute of Science. This Open Access article is under the CC BY-NC license.
http://creativecommons.org/licenses/by-nc/4.0/

## 1. Introduction

Metal matrix composites are important class of materials, which contain metal or alloy as matrix and a ceramic particulate or fiber or whiskers as reinforcements. Aluminium based Metal Matrix Composites exhibit enhanced corrosion resistance, wear and mechanical properties. They provide significantly enhanced properties over metals and alloys. They are used for applications in aerospace, power utility, automotive, and military sectors 1- 2. MMCs reinforced with short fibers offer outstanding specific strength and stiffness along the fiber direction when compared to those with particulate reinforcements that have more isotropic properties. Most research on particulate reinforced MMCs has focused on their manufacturing and mechanical properties 3-4.Relatively little research has been conducted on their corrosion behaviour, and therefore, corrosion mechanisms are not well understood. Conflicting data and interpretations exist regarding fundamental issues, such as corrosion initiation sites and the role of reinforcement in corrosion susceptibility [8-10].Corrosion can affect the metal matrix composite in a variety of ways which depend on its nature and the environmental conditions prevailing. Studying corrosion resistance of Al-based materials is important especially for automotive and aircraft applications. The major advantages of Aluminium 7075 composites compared to

* Corresponding author
E-mail address: pruthvirajrd@gmail.com

unreinforced materials areas follows: greater strength, improved stiffness, reduced density, good corrosion resistance, improved high temperature properties, controlled thermal expansion coefficient, thermal/heat management, improved wear resistance and improved damping capabilities5-6. One of the main disadvantages in the use of metal matrix composite is the influence of reinforcement on corrosion rate. This is particularly important in aluminium alloy based composites, where a protective oxide film imparts corrosion resistance. The present work is focused on corrosion characteristics of Aluminium 7075/ SiC metal matrix composites.

## 2. Materials Selection and Method

The material selected for the present research work is popularly used Aluminium 7075 alloy which is commercially available. Its composition is given in table 1.

**Table 1.** Composition of Aluminium 7075 alloy.

| Element | Cu | Cr | Mn | Mg | Si | Ti | Zn | Fe | Al |
|---|---|---|---|---|---|---|---|---|---|
| Percentage | 1.8 | 0.2 | 0.4 | 1.9 | 0.5 | 0.15 | 3.25 | 0.5 | Bal |

The reinforcement used in the present research work is 50-80µM size Silicon Carbide particulates which is commercially available.

The mediums used for corrosion testing are 0.025M, 0.05M and 0.1 M solution mixtures of sodium hydroxide and sodium chloride.

The method used for corrosion characterization is static weight loss corrosion method as per ASTM standards G69-80.

## 3. Composite Preparation

The composites are prepared by liquid melt metallurgy technique used by Krupakara et al7. Pre heated and uncoated Silicon Carbide particulates are added to molten aluminium 7075 alloy. Composites containing 2, 4 and 6 weight percentage of Silicon Carbide particulates are prepared. Aluminium 7075 alloy is also casted in the same way for comparison. Castings are taken in the form of cylindrical bar.

## 4. Specimen Preparation

The specimen are prepared from the bar castings. Cylindrical specimen of size 20 mm x 20mm are machined from the bar castings of the composites and the matrix alloy. All the specimens are subjected to standard metallographic techniques as done by S. EzhilVannan and Paul Vizhian Simson8 before subjecting them to static weight loss corrosion tests.

## 5. Microstructures

Before subjecting the specimens for corrosion test by weight loss method they are subjected microstructural studies using scanning electron microscope.




**Fig. 1.** Microstructure of Matrix.




**Fig. 2.** Microstructure of 2 % composite.




**Fig. 3.** Microstructure of 4% composite.




**Fig. 4.** Microstructure of 6% composite.

Figures 1-4 show the microstructures of Aluminium 7075 matrix alloy and the composites prepared as per above mentioned procedures. In the figures 1 to 4 uniform

distribution of Silicon Carbide is observed.

## 6. Results and Discussions

The results of weight loss corrosion tests in different concentrated solution mixtures of sodium hydroxide and sodium chloride are given in the figures 6-8.




**Fig. 5.** Results of the test in 0.025M mixture.




**Fig. 6.** Results of the test in 0.05M mixture.




**Fig. 7.** Results of the test in 0.1M mixture.

Figures 5-7 show the results obtained for the static weight loss corrosion test of Aluminium 7075 / Silicon Carbide composites and the matrix alloy in 0.025M, 0.05M and 0.1m solution mixtures respectively for different times of exposure. The results can be discussed under the topic effect of time of exposure and effect of Silicon Carbide content.

## 7. Effect of Time of Exposure

The trend observed in all the cases show decrease in corrosion with increase in test duration. It is clear from the graphs that the resistance of the composite to corrosion increases as the exposure time increases. This eliminates the possibility of hydrogen bubbles clinging on to the surface of the specimen and forming a permanent layer affecting the corrosion process. The phenomenon of gradually decreasing corrosion rate indicates the possible passivation of the matrix alloy. De Salazar9 explained that the protective black film consists of hydrogen hydroxy chloride, which retards the forward reaction. Castle etl. Al.10pointed out that the black film consists of aluminium hydroxide compound. This layer protects further corrosion in acid media. But exact chemical nature of such protective film still is not determined.

From the Fig 5 to 7 it can be clearly observed that for both as cast and composite, corrosion rate decreases monotonically with increase in Silicon Carbide content. In the present case, the corrosion rate of the composites as well as the matrix alloy is predominantly due to the formation of pits and cracks on the surface. In the case of base alloy, the strength of the corrosion medium used induces crack formation on the surface, which eventually leads to the formation of pits, thereby causing the loss of material. The presence of cracks and pits on the base alloy surface was observed clearly. Since there is no reinforcement provided in any form the base alloy fails to provide any sort of resistance to the acidic medium. Hence the weight loss in case of unreinforced alloy is higher than in the case of composites.

Silicon Carbide being the ceramic remains inert and is hardly affected by any medium during the test and is not expected to affect the corrosion mechanism of the composite. The corrosion result indicates an improvement in corrosion resistance as the percentage of Silicon Carbide particulates increased in the composite, which shows that the Silicon Carbide particulates directly or indirectly influence the corrosion property of the composites. Krupakara P.V.11who obtained similar results in glass short fiber reinforced ALUMINIUM 7075 alloy composites reported that the corrosion resistance increases with increase in reinforcement.

Wu.Jinaxin et.al12 in their work on corrosion of aluminium based particulate reinforced MMCs, state that the corrosion is not affected to a significant extent by the presence of Silicon Carbide particulates in aluminium, whereas the particulates definitely play a secondary role as a physical barrier as far as MMC corrosion characteristics are concerned. A particulate

acts as a physical barrier to the initiation and development of corrosion pits and also modifies the microstructure of the matrix material and hence reduces the rate of corrosion.

One more reason for the decrease in corrosion rate is the intermetallic region, which is the site of corrosion forming crevice around each particulates, which may be due to formation of magnesium inter- metallic layer adjacent to the particulate during manufacture as discussed by J.F.Mclyntyre et al13 further showed that the magnesium inter-metallic compounds are more active than the alloy matrix. Pitting in the composites is associated with the particulate matrix interface, because of the higher magnesium concentration in this region. With increase in time pitting would continue to occur at random sites on the particulate matrix interface. The active nature of the crevices would cathodically protect the reminder of the matrix and restrict pit formation and propagation.

## 8. Conclusions

The Silicon Carbide content in Aluminium 7075 alloys plays a significant role in the corrosion resistance of the material. Increase in the percentage of Silicon Carbide will be advantageous to reduce the density and increase in the strength of the alloy, but the corrosion resistance is thereby significantly increased.

Aluminium 7075 MMCs when reinforced with Silicon Carbide of weight percentage from 0 to 6% could be successfully produced by liquid melt metallurgy technique.

The rate of corrosion of both the alloy and composite decreased with increase in time duration in all concentrations of sodium hydroxide and sodium chloride solutions.

The corrosion rate of the composites was lower than that of the corresponding matrix alloy in concentrations of sodium hydroxide and sodium chloride solution

## Acknowledgement

Author wish to thank the Management of RRCE & Principal for the encouragement given to this Research Work.

## References

[1] H.E. Deve, C. McCullough, Continuous-fiber reinforced Al composites: A new generation, JOM 47 (1995) 33-37.

[2] V.V. Vikulin, I.Y. Kelina, A.S. Shatalin, L.N. Rusanova, Advanced ceramic structural materials, Refract. Ind.Ceram. 45 (2004) 383-386.

[3] R. Asthana, M. Singh, N. Sobczak, The role of wetting and reactivity in infiltration of ceramic-metal composites, Ceram. Eng. Sci. Proc. 26 (2005) 249-261.

[4] A. Vassel, Continuous fibre reinforced titanium and aluminium composites: A comparison, Mater. Sci. Eng. A 263 (1999) 305-313.

[5] T.P.D. Rajan, R.M. Pillai, B.C. Pai, Reinforcement coatings and interfaces in aluminium metal matrix composites, J. Mater. Sci. 33 (1998) 3491-3503.

[6] J. Rodel, H. Prielipp, M. Knechtel, N. Claussen, Better ceramics through metal modification, Trans. Mater. Res. Soc. Jpn. 19B (1994) 763-776.

[7] S. EzhilVannan and Paul Vizhian Simson, Corrosion Behaviour of Short Basalt Fiber Reinforced with Al7075 Metal Matrix Composites in Sodium Chloride Alkaline Medium, J. Chem. Eng. Chem. Res.1(2), (2014), 122-131

[8] J.M.G.DeSalazar, A.Urefia, S.Mazanedo and M.Barrens, Corrosion behaviour of AA6061 and AA7075 reinforced with Al2O3 particulates in aerated 3.5%chloride solution potentiodynamic measurements and microstructure evaluation, Corrosion Science, 41, (1999), 529-545.

[9] J.E.Castle, L.Sun and H.Yan,The use of scanning auger microscopy to locate cathodic centers in SiC/Al6061 MMC And to determine the current density at which they operate, Corrosion Science, 36(6), (1994), 1093-1110

[10] Krupakara, P. V, Corrosion Characterization of Al6061/Red Mud Metal Matrix Composites, PortugaliaeElectrochimicaActa 31(3), (2013),157-164

[11] Wu.Jianxin, Liu Wei LiPeng Xing &Wurenjie, “Effect of matrix alloying elements on the corrosion resistance of C /Al composites materials, Jr. of Mat.Sci. lett. 12, (1993).1500-1501

[12] J.F.Mclyntyre, R.K.Conrad&S.L.GoHedge, "Technical note: The effect of heat treatment on the pitting behaviour of SiC / AA2124", Corrosion, vol 46, 190-192.